

8.5 TCAS (RA)

- Follow TCAS commands immediately
- Disconnect autopilot if required

Revision #2

Created 2026-03-23 19:47:41 UTC by Jonas

Updated 2026-03-23 19:48:08 UTC by Jonas